



MACHINE DIRECTION

MACHINE DIREC




SECTION A-A

FIG. 1C




SIDE VIEW


FIG. 1D




F16.2




F16.3



F16 4



F16.5



F16. 6




FIG. 7





FIG. 8








FIG. 10








FIG. /3




FIG. 14






FIG. 15



AT .032 ENGAGEMENT




7° WALL ANGLE CENTERED ALIGNMENT

FIG. 17A



9° WALL ANGLE CENTERED ALIGNMENT


FIG. 178



11° WALL ANGLE CENTERED ALIGNMENT

FIG. 17C

AT .028 ENGAGEMENT




7° WALL ANGLE CENTERED ALIGNMENT

FIG. 18A



9° WALL ANGLE CENTERED ALIGNMENT


FIG. 18B



11° WALL ANGLE CENTERED ALIGNMENT


FIG. 18C

AT .024ENGAGEMENT




7° WALL ANGLE CENTERED ALIGNMENT

FIG. 19A




9° WALL ANGLE CENTERED ALIGNMENT


FIG. 19B



11° WALL ANGLE CENTERED ALIGNMENT

FIG. 19C








FIG. 22A




FIG. 22B




FIG. 22.C







FIG. 22D




F16.23




F16. 24




F16.25




F14.26



F16.27




F16.28



F16.29


```
\alpha
10=I0=I0
1)— [)
```

F16.30




38 40 46


F16. 32



F16.33



F16.34



F16 35




FIG. 36




FIG. 37

